Software history

Main modifications

Each release contains:

- All solutions identified in earlier versions
- Improved connectivity to improve compatibility with other external devices
- This content will also become available in your own language.
- The latest software solves the issues or add new features as indicated below:

Q55xx_0.140.48.0(Publication date: 2012-06-13)

- not possible to access NetTV due to country Selection. (Ukraine)

Q55xx_0.140.47.0(Publication date: 2012-03-14)

- Long movies will not play until the end.(not a download issue)
- Loss of services from channel grid in DVB-S when using ECO-Multiswitch.

Q55xx_0.140.46.0(Publication date: 2011-12-21)

- Solution stuttering noise on HDMI.
- Solution about visible artefacts.

Q55xx_0.140.45.0(Publication date: 2011-12-19)

- Solution for No HD+services anymore possible when provider driven SW update is done.(Germany,Austria and Switserland)
- Solution Mettalic sound when switching between SD and HD sources.

Q55xx_0.140.44.0(Publication date: 2011-12-08)

- Solution for audio drops and mutes with DVB-S boxes from Polsat.
- Solution for Video picture disturbances / freezes on two DVB-C HD services on Eltrona Luxembourg network.
- Solution for sudden volume changes on Bose HCS systems via SPDIF.
- Solution for sound lost in combination with specific Hotel STB.
- Solution for slow respond of TV RC keys.

Q55xx_0.140.40.0(Publication date: 2011-08-24)

- Solution to activate Net TV in a better way.

Q55xx_0.140.39.0(Publication date: 2011-07-15)

- Solution for lost of presets after toggling between ASTRA and HOT Bird (between 2LNBs).
- Solution for picture disturbance on DVB-C channel'Phoenix'-Germany region Zweibrucken.

- Solution for lipsync on EXT, 'audio uitvoer delay' not working.
- Solution for when starting up sometimes no picture.
- Solution for Russian translation errors in UI and Net TV.
- Solution for set goes auto to standby after 2h startup in the morning, RiksTV Norwegian DVB-T network.

Q55xx_0.140.37.0(Publication date: 2011-06-09)

- Solution for the 40PFL9705K/02 + all TV550 - OSD "videoformat not supported",with WISI STB OR194.
- Solution for Finland Welho Cable network: no video decoded on mosaic channels.
- Solution for 2nd language drops back to first language after some time.
- Solution for 32PFL7605H/60, 40PFL8605H/60, problem with letters in Net TV.
- Availability for Latvia about DVB-T full profile.

Q55xx_0.140.36.0(Publication date: 2011-05-13)

- Small picture of TV channel in right upper corner after going to NetTV.
- Solution for ZDF/ARD Mediathek playback freeze after 20min.
- Solution for MPEG artifacts in HD channels La Sexta Spain.
- Solution for no txt after open internet usage or during use of external.
- Solution for special characters in Portuguese multitab via RC.
- Solution for coloured semi-transparant layers in nettv and txt.
- Solution for problems with technisat HD8+ HD stb.
- Solution for EPG starts always on channel 1.
- Solution for movie in videostore stops after 2h33.

Q55xx_0.140.34.0(Publication date: 2011-04-11)

- Intermittent sound lost while watching TV or a connected device via HDMI.
- Macro-blocks appear on digital (DVB-T) channels with HD content. (Only applicable to country, Spain)

Q55xx_0.140.32.0(Publication date: 2011-03-04)

- Intermittent sound lost while watching TV or a connected device via HDMI.
- Slow in switching between digital cable (DVB-C) channels.
- Macro-blocks appear on digital (DVB-T) channels.

Q55xx_0.140.29.0(Publication date: 2011-02-22)

- To enable the TV to accept Com Hem CAM software upgrade via OAD. (Only applicable to country, Sweden)

Q55xx_0.140.27.0(Publication date: 2011-01-05)

- Solution for intermittent freezing picture in Finland.
- Solution for zapping away from 3D broadcast channel in the Netherlands that results in no video.
- Solution for intermittent disturbance on audio via SPDIF out.
- Solution to prevent random services installation on UPC cable com in Switzerland.
- Solution to avoid that the set is rebooting/dead after sw update via PTA02 by packed stick.
- Solution for distorted sound with certain video formats playing via HDMI.
- Solution about the issue when the Double Video MHP application "GF Pay" is killed and is switching from secondary to primary video.
- Solution for installing Dig DVBC , DVB-C when 170MHZ in MUX, picture is distorted.
- Solution for sound drops.

Q55xx_0.140.25.1(Publication date: 2010-11-23)

- Fix-visible bright lines at the right border in the 58PFL9955H/12.

Q55xx_0.140.25.0(Publication date: 2010-11-08)

- Improvement on zapping performance.
- Fix- Restart of the set when putting in standby.
- Improvement on zapping on 3D channels on cable.
- Improvement on support of new NetTV service portal.

Q55xx_0.140.23.0(Publication date: 2010-10-20)

- Fix- TV is intermittently switching to standby after 2-3 Hr.
- Fix- Combined satellite tuner reboots visible.
- Fix- When accessing NetTV the interface language is always in English independent of the system menu language selected by user.
- Fix- Finland -Intermittent functioning of teletext and subtitles
- Fix- Video playback (USB/DLNA/nettv) → Picture format now takes into account the video aspect ratio instead of the standard container aspect ratio. Result: Videos with aspect ratio different than 16:9 are not going to be stretched anymore by default.
- Fix- Picture judders during playback via USB.

Q55xx_0.140.11.0(Publication date: 2010-10-05)

- DVB-S:pre-defined channel grid in Austria and Switzerland implemented.
- Improvements on picture performance in general.
- Improvement for the EPG broadcast performance and channel list on KDG cable network.(for Germany)
- Improved behavior of video store.
- Startup behavior is improved.
- Enhanced robustness again remote controls of other devices.
- Possible audio loss solved on HDMI and DVB-T Spain.
- Widget icon is no longer present in the menu.

Q55xx_1.75.60.1

- Ziggo certification obtained.

Q55xx_1.75.59.0

- Improvements on subtitles level for BBC1 and UPC.
- Reduces possible transients after channel change.
- Solves possible loss or dark picture at startup or after channel change.
- Improves ambilight stability.
- Improvements on sorting on digital channels in Germany.
- Improvements on MPEG4 playback.
- Improvements on teletext in Danmark and the Netherlands.

Q55xx_1.75.13.54

- Improvements for broadcasting in Switzerland.
- HDMI audio improvements in general and especially for Belgium concerning Belgacom box.
- Adaptation menu items Germany.
- Support of Video Store.

Q55xx_1.75.13.47

- Improvement on the level of the startup behaviour.

Q55xx_0.75.13.43

- improvements on the multimedia features.